2023 Trackside Information – NJMP

The Track will be open at 7:00 AM. Registration will be open by 7:30 AM. Trackside Tech Inspection opens at 7:30 AM. Upon arriving, promptly prepare your car for trackside tech inspection. (**Note**: this tech inspection does not replace the pre-event tech inspection, **which must be done by a PCA Region approved tech site prior to this event.)** All participants, including instructors, must check-in prior to tech inspection and **MUST** have a run group wristband **BEFORE** going through tech. All instructor assignments will be given out after the Driver's Meeting

Attendance at the driver's meeting is mandatory for ALL drivers.

You will need your valid PCA Membership card along with a valid driver's license. **We WILL be checking Driver's Licenses at registration... please have them ready!**

It is mandatory for all Boxsters, Cabriolets, Roadsters and Speedsters to have roll bars that meet minimum height requirements or have a Hard Top in place. If you plan on running with the top down, proper arm restraints must be used.

NJMP requires open cars to have deployed roll-over protection

Long trousers are required while driving. Natural fibers are preferable. Suitable closed toe shoes like sneakers must be worn.

Snell 2015 or newer helmets are required.

PLEASE NOTE: Full face helmets are a NJ State requirement. One exception is if the car is street legal and has air bags, then an open face helmet may be used. All Aftermarket harnesses MUST be kept up to date. Most have a 5 year expiration on the webbing. If the webbing is out of date, you will not be allowed to use it on track.

High-octane fuel is usually available at the track. Regular gas must be purchased outside the track facilities.

Only registered drivers are permitted on the track. No passengers except for instructors. A driver is permitted on the track only during his/her assigned run group.

Metro NY PCA sponsors this event as a drivers' education event. It is not a race or a race school. We encourage all participants to enjoy the experience and bring a mature, cooperative and not overly aggressive attitude to the event. Participants engaging in inappropriate actions are subject to having their registration canceled, at the discretion of Metro NY PCA.

Driver is responsible for any/all track damage they may cause.

Registrar must receive notice of cancellation at least one week before the event.

If you have any questions please call (516) 801-1331, a voice-only number - or email: MetroNYPCADE@gmail.com

Trackside Checklist

Extra oil and brake fluid.

Insect repellant.

Large plastic bags to store everything you do not want to get wet in the event of rain. This will also allow you to keep everything in one place.

Painters tape for headlights and fog lights so they don't get chipped or cracked from loose grit on the track.

Weather is unpredictable - be prepared for cool or warm, dry or wet.

Rain gear - Yellow and Red must be avoided for flagging reasons.

Sun protection gear (hat, umbrella, sunscreen, etc.)

Long pants for driving, natural fibers advised.

Suitable closed toe shoes like sneakers should be worn. No shorts, sandals or loose fitting shoes.

An air gauge for checking tire pressure, a torque wrench for checking wheel torque and masking tape for numbers are all a plus to make your day go easier.

HYDRATION IS VITAL! This is even true on a cool day. Bring food and drink in case the snack bar is not open. No alcoholic beverages or controlled substances are permitted anywhere on track premises.

Numbers must be placed on each side of the car and the rear window, without blocking your outward vision. Numbers on the front windshield (passenger side) will be appreciated. This can be done with white shoe polish or you can create numbers before you arrive at the track. Many people use tape to create temporary numbers.

Numbers must be applied to the car prior to tech. The numbers on the car must match your assigned number as shown on your registration confirmation, and as shown on yout tech sheet.